Allstate Peterbilt of Alexandria

6307 County Road 87 SW Alexandria, Minnesota 56308
Phone: (320) 759-3947

Case Number: 21262475
Repair Order Number: 142359
Purchase Order Number: N/A
Service Advisor: Courneya, Chase - Case Date 2026-09-22 10:48:44 -0500
ETR: 9/22/2026 at 05:03 pm CDT

Customer: Carlos Fire Department

Unit Number: N/A

2AJ89418

Address: PO BOX 276 CARLOS, MN 56319-0276
Phone: (320) 762-8151
Fax: N/A
Customer Number: 72736
Billing Customer: City Of Carlos

Asset: 2002 Sterling L [L8500]
Serial Number: 2AJ89418
VIN: 2FZAAWAK32AJ89418
Engine: Not Supported

Engine Hours: 7920
Odometer: 182087 Miles
Warranty Start: N/A
In Service: N/A

1 BRAKE CHAMBER

Complaint: LEFT REAR BRAKE CHAMBER SPRING COMING THROUGH PUSH ROD HOLE

		Quantity	Price	Totals
Labor:			$186.00	$186.00
Parts:	CHAMBER-BRAKE 2.25, LS, FL N	1.0	$122.74	$122.74
Additional Charges:	Shop Sup1, Service Shop Supplies	n/a	$18.41	$18.41
Operation Total:				**$327.15**

2 STEERING AXLE BRAKES (2)

Complaint: RIGHT STEER AXLE BRAKES SEPARATING

		Quantity	Price	Totals
Labor:			$186.00	$186.00
Parts:	KIT-BRAKE FM SELECT 16.5X6 23K PREM	1.0	$120.86	$158.36
Additional Charges:	Shop Sup1, Service Shop Supplies	n/a	$18.41	$18.41
Operation Total:				**$362.77**

3 AIR SYSTEM

Complaint: OIL IN INSIDE LOWER RIGHT AIR TANK - AIR COMPRESSOR PASSING OIL

		Quantity	Price	Totals
Labor:			$186.00	$2,976.00
Parts:	COMPR GP-B	1.0	$2,778.25	$2,778.25
Additional Charges:	Shop Sup1, Service Shop Supplies	n/a	$294.62	$294.62
Operation Total:				**$6,048.87**

ESTIMATE

Allstate Peterbilt of Alexandria

Customer: Carlos Fire Department	**Unit Number:** N/A
Case Number: 21262475	**Asset:** 2002 Sterling L [L8500] **VIN:** 2FZAAWAK32AJ89418

2AJ89418

Parts	$3,021.85
Labor	$3,348.00
Shop Sup1	$331.44
Taxes	$225.63
Core	$37.50
Total	**$6,964.42**

This estimate is subject to teardown and inspection and is valid for 30 days from date above. I, the undersigned, authorize you to perform the repairs and furnish the necessary materials. I understand any costs verbally quoted are an estimate only and not binding and that this estimate does not include any applicable computer diagnostic hookup fees or charges. I understand that there may be an additional charge for freight under extenuating circumstances. I understand that if I choose to pay by credit card, a convenience fee may apply to the final charges. Your employees may operate vehicle for inspecting, testing and delivery at my risk. You will not be responsible for loss or damage to vehicle or articles left in it.

ESTIMATE